## CERTIFICATE

International School, Shimla has been inspected by me along with Junior Engineer concerned on during 15.03.2022 and to report that the owner of this building .Shri Vishal Chauhan, & Smt Chanderesh Kumari, C/O Sanvi Education Society) the building is RCC frame structure. This building appears to safe visually for occupancy. The structure stability certificate cannot be issued because this building has not been constructed by the HPPWD.

This Certificate is issued for the session 2022-23.

Dated 31.03.2022

Assistant Environm, Shimbs Rubs Division No. I H.P.P.W.D., Sh.S. 18-3

Executive Engineer Shimla Division No.1